


Page 1

From Aug 01, 2017 to Mar 29, 2018


ECTS--Audit - Lab/Classroom Safety (22 walkthroughs)


Evacuation plan is posted in plain sight	Total	%	
■ Selected	22	100%	
■ Not selected	0	0%	
Compliant/Non-Compliant (Based on 22 walkthroughs)			
■ 1. Compliant		22	100%
■ 2. Non-Compliant		0	0%
■ 3. Not Applicable		0	0%




Access to fire alarm boxes are clear		Total	%	
 Selected		22	100%	
 Not selected		0	0%	

Compliant/Non-Compliant (Based on 22 walkthroughs)			Selected	%
 1. Compliant			11	50%
 2. Non-Compliant			0	0%
 3. Not Applicable			11	50%




Access to fire extinguishers is clear		Total	%	
■ Selected		21	95.5%	
■ Not selected		1	4.5%	

Compliant/Non-Compliant (Based on 22 walkthroughs)			Selected	%
■ 1. Compliant			22	100%
■ 2. Non-Compliant			0	0%
■ 3. Not Applicable			0	0%




Fire exits are open		Total	%	
 Selected		22	100%	
 Not selected		0	0%	

Compliant/Non-Compliant (Based on 22 walkthroughs)			Selected	%
 1. Compliant			20	90.9%
 2. Non-Compliant			0	0%
 3. Not Applicable			1	4.5%




Fire exits are unlocked from interior of building		Total	%	
■ Selected		22	100%	
■ Not selected		0	0%	

Compliant/Non-Compliant (Based on 22 walkthroughs)			Selected	%
■ 1. Compliant			21	95.5%
■ 2. Non-Compliant			0	0%
■ 3. Not Applicable			1	4.5%




Emergency stop buttons are clear and accessible		Total	%	
■ Selected		22	100%	
■ Not selected		0	0%	

Compliant/Non-Compliant (Based on 22 walkthroughs)			Selected	%
■ 1. Compliant			10	45.5%
■ 2. Non-Compliant			0	0%
■ 3. Not Applicable			12	54.5%




Safety glasses are worn by students	Total	%	
■ Selected	22	100%	
■ Not selected	0	0%	

Compliant/Non-Compliant (Based on 22 walkthroughs)		Selected	%
■ 1. Compliant		16	72.7%
■ 2. Non-Compliant		0	0%
■ 3. Not Applicable		6	27.3%




Safety glasses are worn by staff		Total	%	
 Selected		22	100%	
 Not selected		0	0%	

Compliant/Non-Compliant (Based on 22 walkthroughs)			Selected	%
 1. Compliant			16	72.7%
 2. Non-Compliant			0	0%
 3. Not Applicable			6	27.3%




Extension cords are used only were necessary		Total	%	
 Selected		22	100%	
 Not selected		0	0%	

Compliant/Non-Compliant (Based on 22 walkthroughs)			Selected	%
 1. Compliant			22	100%
 2. Non-Compliant			0	0%
 3. Not Applicable			0	0%




Extension cords are clear of walkways		Total	%	
■ Selected		22	100%	
■ Not selected		0	0%	

Compliant/Non-Compliant (Based on 22 walkthroughs)			Selected	%
■ 1. Compliant			22	100%
■ 2. Non-Compliant			0	0%
■ 3. Not Applicable			0	0%




Machine guards are on machines		Total	%	
■ Selected		22	100%	
■ Not selected		0	0%	

Compliant/Non-Compliant (Based on 22 walkthroughs)			Selected	%
■ 1. Compliant			10	45.5%
■ 2. Non-Compliant			0	0%
■ 3. Not Applicable			12	54.5%




Machine guards are in working order		Total	%	
 Selected		22	100%	
 Not selected		0	0%	

Compliant/Non-Compliant (Based on 22 walkthroughs)			Selected	%
 1. Compliant			10	45.5%
 2. Non-Compliant			0	0%
 3. Not Applicable			12	54.5%




Tool rests are available		Total	%	
■ Selected		22	100%	
■ Not selected		0	0%	


Compliant/Non-Compliant (Based on 22 walkthroughs)			Selected	%
■ 1. Compliant			9	40.9%
■ 2. Non-Compliant			0	0%
■ 3. Not Applicable			13	59.1%




Blade guards are in place		Total	%	
■ Selected		22	100%	
■ Not selected		0	0%	

Compliant/Non-Compliant (Based on 22 walkthroughs)			Selected	%
■ 1. Compliant			4	18.2%
■ 2. Non-Compliant			0	0%
■ 3. Not Applicable			18	81.8%




Tanks are secured to wall or fixture		Total	%	
■ Selected		21	95.5%	
■ Not selected		1	4.5%	

Compliant/Non-Compliant (Based on 22 walkthroughs)			Selected	%
■ 1. Compliant			3	13.6%
■ 2. Non-Compliant			0	0%
■ 3. Not Applicable			18	81.8%




Doors are closed when area is not in use		Total	%	
■ Selected		22	100%	
■ Not selected		0	0%	

Compliant/Non-Compliant (Based on 22 walkthroughs)			Selected	%
■ 1. Compliant			20	90.9%
■ 2. Non-Compliant			0	0%
■ 3. Not Applicable			1	4.5%




Doors are locked when area is not in use		Total	%	
■ Selected		22	100%	
■ Not selected		0	0%	

Compliant/Non-Compliant (Based on 22 walkthroughs)			Selected	%
■ 1. Compliant			21	95.5%
■ 2. Non-Compliant			0	0%
■ 3. Not Applicable			1	4.5%




Area is clear of trip hazards		Total	%	
■ Selected		22	100%	
■ Not selected		0	0%	

Compliant/Non-Compliant (Based on 22 walkthroughs)			Selected	%
■ 1. Compliant			20	90.9%
■ 2. Non-Compliant			2	9.1%
■ 3. Not Applicable			0	0%




Fire loads are minimized		Total	%	
 Selected		22	100%	
 Not selected		0	0%	

Compliant/Non-Compliant (Based on 22 walkthroughs)			Selected	%
 1. Compliant			22	100%
 2. Non-Compliant			0	0%
 3. Not Applicable			0	0%




Storage occurs off the floor		Total	%	
■ Selected		22	100%	
■ Not selected		0	0%	

Compliant/Non-Compliant (Based on 22 walkthroughs)			Selected	%
■ 1. Compliant			15	68.2%
■ 2. Non-Compliant			5	22.7%
■ 3. Not Applicable			1	4.5%




Overhead storage is avoided		Total	%	
 Selected		22	100%	
 Not selected		0	0%	

Compliant/Non-Compliant (Based on 22 walkthroughs)			Selected	%
 1. Compliant			21	95.5%
 2. Non-Compliant			1	4.5%
 3. Not Applicable			0	0%




Safety Data Sheet book is publicly available		Total	%	
 Selected		22	100%	
 Not selected		0	0%	

Compliant/Non-Compliant (Based on 22 walkthroughs)			Selected	%
 1. Compliant			21	95.5%
 2. Non-Compliant			0	0%
 3. Not Applicable			1	4.5%




First aid kit is publicly available	Total	%	
■ Selected	22	100%	
■ Not selected	0	0%	

Compliant/Non-Compliant (Based on 22 walkthroughs)			Selected	%
■ 1. Compliant			22	100%
■ 2. Non-Compliant			0	0%
■ 3. Not Applicable			0	0%




Eye wash station is operational		Total	%	
■ Selected		22	100%	
■ Not selected		0	0%	

Compliant/Non-Compliant (Based on 22 walkthroughs)			Selected	%
■ 1. Compliant			9	40.9%
■ 2. Non-Compliant			0	0%
■ 3. Not Applicable			13	59.1%



Inspection report reviewed with faculty member		Total	%		
 Selected		22	100%		
 Not selected		0	0%		
Yes/No (Based on 22 walkthroughs)				Selected	%
 1. Yes				21	95.5%
 2. No				0	0%



Corrective action required by faculty member based on inspection		Total	%		
 Selected		22	100%		
 Not selected		0	0%		
Yes/No (Based on 22 walkthroughs)				Selected	%
 1. Yes				5	22.7%
 2. No				17	77.3%

